Material Test Report

Report Number:	681742.00-12		
Issue Number:	1		
Date Issued:	26/11/2020		
Client:	Roberts Bros Pty Ltd		
	123 Cooroy Belli Creek Road, Cooroy 4563		
Contact:	David Roberts		
Project Number:	681742.00		
Project Name:	Proposed Subdivision		
Project Location:	Greendale, Stage 5, Pie Creek		
Work Request:	11184		
Date Sampled:	09/11/2020		
Dates Tested:	10/11/2020 - 12/11/2020		
Sampling Method:	AS 1289.1.2.1 6.4 (b) - Sampling from layers in earthworks or pavement - compacted		
Specification:	Minimum 95% Standard Hilf Density Ratio		
Lot Number:	13		
Material Source:	Onsite		

Douglas Partners Geotechnics | Environment | Groundwater

Douglas Partners Pty Ltd Sunshine Coast Laboratory 1/28 Kessling Avenue Kunda Park QLD 4556 Phone: (07) 5351 0400 Fax: (07) 5351 0499 Email: martin.cook@douglaspartners.com.au Accredited for compliance with ISO/IEC 17025 - Testing

NATA

white

Approved Signatory: Martin Cook Assistant Laboratory Manager NATA Accredited Laboratory Number: 828

Compaction Control AS 1289 5.7.1 & 5.8	.1		
Sample Number	SS-11184A	SS-11184B	
Date Tested	09/11/2020	09/11/2020	
Time Tested	10:20	10:30	
Test Request #/Location	Lot 13	Lot 13	
Easting	461735	461732	
Northing	70966760	7096681	
Elevation (m)	0.8m < F.L.	0.3m < F.L.	
Soil Description	Sandy Clay	Sandy Clay	
Test Depth (mm)	150	150	
Sieve used to determine oversize (mm)	19.0	19.0	
Percentage of Wet Oversize (%)	0	0	
Field Wet Density (FWD) t/m ³	2.01	2.04	
Field Dry Density (FDD) t/m ³	**	**	
Peak Converted Wet Density t/m ³	2.00	1.97	
Adjusted Peak Converted Wet Density t/m	**	**	
Moisture Variation (Wv) %	3.5	2.5	
Adjusted Moisture Variation %	**	**	
Hilf Density Ratio (%)	100.5	103.5	
Compaction Method	Standard	Standard	
Report Remarks	**	**	

Moisture Variation Note:

Positive values = test is dry of OMC Negative values = test is wet of OMC