

Material Test Report



Geotechnics | Environment | Groundwater

Douglas Partners Pty Ltd

Sunshine Coast Laboratory

1/28 Kessling Avenue Kunda Park QLD 4556

Phone: (07) 5351 0400

Fax: (07) 5351 0499

Email: martin.cook@douglaspartners.com.au

Report Number: 205535.00-14
Issue Number: 1
Date Issued: 27/07/2021
Client: Roberts Bros Pty Ltd
 123 Cooroy Belli Creek Road, Cooroy QLD 4563
Contact: John Roberts
Project Number: 205535.00
Project Name: Proposed Subdivision
Project Location: Chatsworth Estate, Stage 4, Chatsworth QLD
Work Request: 13739
Date Sampled: 21/07/2021
Dates Tested: 21/07/2021 - 26/07/2021
Sampling Method: AS 1289.1.2.1 6.4 (b) - Sampling from layers in earthworks or pavement - compacted
Specification: Minimum 95% Standard Hilf Density Ratio
Location: Bulk Earthworks
Lot Number: 72
Material Source: Onsite



Accredited for compliance with ISO/IEC 17025 - Testing

Approved Signatory: Martin Cook

Assistant Laboratory Manager

Laboratory Accreditation Number: 828

Compaction Control AS 1289 5.7.1 & 5.8.1			
Sample Number	SS-13739A	SS-13739B	
Date Tested	21/07/2021	21/07/2021	
Time Tested	11:04	11:15	
Test Request #/Location	Lot 72	Lot 72	
Easting	462856	462866	
Northing	7107970	7107975	
Elevation (m)	0.2 < F.L.	0.55 < F.L.	
Soil Description	Gravelly Clay	Gravelly Clay	
Test Depth (mm)	150	150	
Sieve used to determine oversize (mm)	19.0	19.0	
Percentage of Wet Oversize (%)	6	14	
Field Wet Density (FWD) t/m ³	2.19	2.19	
Field Dry Density (FDD) t/m ³	**	**	
Peak Converted Wet Density t/m ³	**	**	
Adjusted Peak Converted Wet Density t/m ³	2.11	2.23	
Moisture Variation (Wv) %	**	**	
Adjusted Moisture Variation %	2.0	0.0	
Hilf Density Ratio (%)	104.0	98.0	
Compaction Method	Standard	Standard	
Report Remarks	**	**	

Moisture Variation Note:

Positive values = test is dry of OMC

Negative values = test is wet of OMC